

**MP 4.0 60' Deck Plate Girder Over Montour Run at Robbs**

**Mile 3.6 Trail MP 2.8**

Builders Plate: Built by McClintic-Marshall Company Pittsburgh, PA 1924

1/3 mile north of Beaver Grade Road

One of two similar bridges used in realignment of this section of the main line.

View looking west



2010 Photos Bryan Seip

Builder's Plate: Built by McClintic-Marshall Company Pittsburgh, PA 1924



1924 in concrete of both abutments



Satellite view shows bridge just above center of picture. Second bridge of this realignment is at top center.



View looking east





Possible traces of original Right-of-Way following Montour Run along creek bank on far side of bridge.

Deep cut approx 35 ft in rock between bridges 4.0 & 3.8 – dug during realignment and installation of two bridges in 1924.

This bridge is the lower one in this 1938 view.



Courtesy Penn Pilot

Compiled by Montour Railroad Historical Society members